

# Engine Service and Maintenance Record

Total Time

Time Since Last Overhaul

Date

**CONRAD AERO**

1200 Flight Line Dr. Unit 516 Three Rivers, MI 49093

Phone: (269) 279-6000

Engine Log Entry

e part removal and worthiness Directives, ulletins

Date: 7-1-2014

Hobbs Time: 2553.0

SMOH: 0

Removed cowling, and aircraft engine at this time, for replacement with factory rebuilt unit P/N TSIO550C14, Found engine mount cracked at this time, removed cracked mount and installed rebuilt TSIO 550 mount from Acorn. Installed factory rebuilt engine to include new spark plugs, hoses, #1 alternator, lord mounts, turbos, intercoolers, exhaust, air cleaner and alternator belt. Also one new vacuum pump P/N 442CW-4. Drained pickling oil from engine, put 8 qts of Aeroshell 100 straight mineral oil (due change in 25hrs). Turned engine over by hand until oil pressure achieved. Started engine and did first run, oil press came up instantly, shut down and inspected for leaks, no leaks noted. Cowled engine and performed engine runs and adjustments as required, no defects noted. I certify this engine has been inspected in accordance with an annual inspection and was found to be in airworthy condition at this time.

*Jason Jones*

A&P 3142013 IA

*OIL CHANGE*

*OIL CHANGE*